


Foundation Excavations Northwest Church Wall June 1987








————— Foundation —————

Design of Spread Footing for Christ Church

(Bricks are $4 \times 8\frac{1}{2} \times 2\frac{3}{4}$)



old level of brick - 4" (Present earth level)
old level of concrete

7 courses @ $\frac{1}{2}$ " offset

4 courses @ 2" offset

3 courses @ $\frac{1}{2}$ " offset

3 courses @ 0" offset

clay for undetermined depth

Total depth approximately 6'0"

(Wall of Church said to be 36" thick, so with 26" flairs at the bottom, the wall base was almost 6' thick)

VN 22/6/87